



Sprso Giro Troubleshooting

Error	The display shows Brewer malfunction (Error 04104) after you have opened the side panel.
Action	Close the side panel, and reset the machine by unplugging the power cord.
Remark	This error may occur when you open the side panel while the brewer has not fully completed a brewing cycle (and is still in motion).



Remount/close the side panel.



Reset de machine: Remove the power plug for 5 seconds, and reconnect.

Caution: Do not perform with wet/moist hands.



Always wait until the brewing cycle is fully completed, before opening the side panel. The brewer is still in motion (3-5 sec) after a coffee has been dispensed.



The message **Brewer malfunction (Error 04104)** will be resolved in most cases. Should it remain, see also ***Brewer malfunction (Error 04104) when remounting the brewer*** for more information.

Do you have any questions or does the problem persist? Please contact the helpdesk of your local service organization.